

Government of Jammu & Kashmir
Office of the Executive Engineer, Muffasil (R&B) Division, Budgam.

No.
Dated: 5945-46

27-7-2021

✓ The Principal,
Jawahar Navodaya Vidyalaya,
Budgam.

Subject: Building Safety Certificate.


Sir,

As reported by Assistant Executive Engineer (R&B) Sub-Division, Budgam. The single storey building of Jawahar Navodaya Vidyalaya situated at Khanpora Budgam apparently /superficially seems in good condition . However, it can't be ascertained, whether the building /structure has been constructed as per earthquake resistant parameters.

The condition of the building is defined in following sections.

1	Type of surrounding & soil in the area	Open area with normal soil
2	Type of foundation	R.S. Masonry
3	Type of super structure	Load bearing brick work in cement mortar
4	Type of roofing	C.G.I Sheet Roofing
5	Condition of bath rooms	Functional and in good condition
6	Safety features such as grills/fences/fire fighting and electrical	Provided
7	Emergency exists in case of fire /earth quakes	Provided
8	Photographs	Enclosed
9	Date of Inspection	19/07/2021.

Yours Faithfully,


Executive Engineer,
Muffasil (R&B) Division, Budgam
Muffasil (R&B) Division
Budgam

Copy to the:

1. Assistant Executive Engineer (R&B) Sub Division Budgam for information. This is with reference to his letter NO: SDB/549 dated: 26/07/2021..